

Product Safety Recall



Recalled

Not recalled

Thermos Stainless King Food Jars - 470ml and 710ml

Model Nos: SK3000 & SK3020

Sold between approx. August 2013 and December 2022
at Briscoes Seymour, Mitre 10, and Moore Wilson

Defect: In certain circumstances, pressure may build up inside the container which may cause the stopper beneath the lid to eject forcefully without warning when opened. This may occur if contents are left in the container for an extended period, contrary to the product's intended use.

Hazard: Lid may eject forcefully without warning when opened.

What to do: Check if the underside of the stopper has a pressure relief feature (see picture provided). If not, you have an affected product and Thermos will provide a replacement stopper at no cost when contacted by you. When contacting Thermos, please provide your name, contact details, postal address, and a photograph of the underside of the stopper to verify the product is an affected product. You should not use the product until the replacement stopper has been installed.

Contact details:

phone: +61 2 8853 5400

email: info@thermos.com.au

online: <https://www.thermos.com.au/recall/>

New Zealand Importer/Distributor

Thermos Pty Ltd
Unit 318/14-16 Lexington Drive
Norwest Business Park
Bella Vista, NSW 2153
Australia
+61 2 8853 5400

See www.recalls.govt.nz for
other New Zealand consumer product recalls